



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	<b>-21</b>	TSN:	<b>9,473.1</b>	TSO:	<b>0.0</b>	W/O#:	<b>7996</b>
PCE:	<b>24568</b>	CSN:	<b>7,433</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	1B113	12,501	6,499
Disk, 2 <sup>nd</sup> Stg.	3013712	5M755	18,200	5,800
Disk, 3 <sup>rd</sup> Stg.	3011713	6496	18,521	6,479
Impeller	3013176	2A425	12,501	6,499
Disk, CT	3013411	8L458	8,929	7,071
PT Disk, 1 <sup>st</sup> Stg.	3022412	8A379	12,990	7,010

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	18463768	0.0
FUEL PUMP	025323-101-03	6926	0.0
FUEL CONTROL UNIT	3244745-4	A72652	0.0
FLOW DIVIDER/ DUMPVALVE	3019906/25536-4	9959513217	0.0
OIL/FUEL HEATER	10552E	WA44879	0.0
COMP. BLEED VALVE	3100829-03	7C440	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.