



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	13,724.47	TSO:	0.0	W/O#:	7658
PCE:	40490	CSN:	17,184	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	TBA	9,000	10,000
Disk, 2 nd Stg.	3013712	A2166	14,057	9,943
Disk, 3 rd Stg.	3011713	B1552	15,635	9,365
Impeller	3013176	4A744	2,352	16,648
Disk, CT	3013411	6A958	7,433	8,567
PT Disk, 1 st Stg.	3026812	62A483	11,592	8,408

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	1749551	0.0
FUEL PUMP	025323-101-02	R1272D	0.0
FUEL CONTROL UNIT	2524440-7-6	A59043	0.0
START FLOW CONTROL	3019109	11024	0.0
OIL/FUEL HEATER	10552E	5636	0.0
COMP. BLEED VALVE	3100829-03	6T737	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.