



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	14,993.7	TSO:	0.0	W/O#:	7712
PCE:	51763	CSN:	16,919	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	9N836	5,885	13,115
Disk, 2 nd Stg.	3013712	13A394	4,892	19,108
Disk, 3 rd Stg.	3011713	31A459	4,892	20,108
Impeller	3013176	8D765	6,151	12,849
Disk, CT	3013411	1L739	4,257	11,743
PT Disk, 1 st Stg.	3022412	9W554	4,892	15,108

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004	2139866	0.0
FUEL PUMP	025323-01	2509	0.0
FUEL CONTROL UNIT	2524440-7-6	2509	0.0
START FLOW CONTROL	3019109	19835	0.0
OIL/FUEL HEATER	UA525193-6	980	0.0
COMP. BLEED VALVE	3100829-03	3H588	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.