



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-45R	TSN:	GG: 23,247.7 PS: 15,509.5	TSO:	GG: 3,060.3 PS: 3,060.3	W/O#:	8147
PCE:	GG: 84250 PS: 84275	CSN:	GG: 30,798 PS: 20,269	CSO:	GG: 4,343 PS: 4,343	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3023611	31A666	10,878	9,122
Disk, 2 nd Stg.	3023112	34A152	10,878	9,122
Disk, 3 rd Stg.	3023113	34A121	10,878	9,122
Impeller	3036793	2E427	10,878	9,122
Disk, CT	3024711	1P593	16,243	3,757
PT Disk, 1 st Stg.	3029312	5N542	15,258	14,742
PT Disk, 2 nd Stg.	3029313	4N276	15,258	14,742

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-209F	2244067	412.3
FUEL PUMP	025323-300-02	5362	3,060.3
FUEL CONTROL UNIT	3244773-5	A67020	3,060.3
OIL/FUEL HEATER	10585	UNKNOWN	UNKNOWN
COMP. BLEED VALVE	3100923-02	6A982	0.0
COMP. BLEED VALVE	3100922-01	8E70	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.