



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	4,985.9	TSO:	3,388.9	W/O#:	7507
PCE:	52434	CSN:	5,613	CSO:	4,125	TSHS:	59.6

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1F534	5,613	13,387
Disk, 2 nd Stg.	3013712	3H548	5,613	18,387
Disk, 3 rd Stg.	3011713	5F609	5,613	19,387
Impeller	3013176	3D514	5,613	13,387
Disk, CT	3013411	1F119	5,613	10,387
PT Disk, 1 st Stg.	3022412	1F047	5,613	14,387

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2491437	97
FUEL PUMP	025323-101-03	8359	1,299.2
FUEL CONTROL UNIT	2524440-8-6	A85449	689.2
START FLOW CONTROL	3019109	9251	2,867.3
OIL/FUEL HEATER	10552E	2788	2,867.3
COMP. BLEED VALVE	3100829-03	36A919	97

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.