



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-65B	TSN:	GG: 11,785.3 PS: 12,034.4	TSO:	GG: 2,462.5 PS: 2,712.6	W/O#:	8370
PCE:	97501	CSN:	GG: 14,287 PS: 14,793	CSO:	GG: 5,197 PS: 5,703	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Shaft Comp. Rotor	3037277	9M924	10,176	4,824
Hub, 1 st Stg.	3037101	99A401	20,838	3,162
Disk, 2 nd Stg.	3036802	4X846	20,858	3,142
Disk, 3 rd Stg.	3036803	7W816	19,542	4,458
Disk, 4 th Stg.	3036804	28A596	21,226	2,774
Impeller	3036794	7D639	14,287	9,713
Disk, CT	3040311	TBA	13,094	1,906
PT Disk, 1 st Stg.	3029312	A8278	27,017	2,983
PT Disk, 2 nd Stg.	3029313	6F130	21,244	8,756

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-212G	2254546	UNKNOWN
FUEL PUMP	399701-5	0199	719.2
FUEL CONTROL UNIT	8061-328	2240989	3,359.3
OIL/FUEL HEATER	10585K-FGHY	764	683.9
COMP. BLEED VALVE	01R3106870-01	3N626	719.2

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

New CT Blades