



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet

PT6A:	-34	TSN:	GG: 15,161.3 PS: 15,161.3	TSO:	GG: 1,492.6 PS: 1,492.6	W/O#:	10626
PCE:	GG: 57025 PS: 57021-100	CSN:	GG: 20,224 PS: 20,224	CSO:	GG: 1,531 PS: 1,531	TSHS:	1,492.6

Life Limited Part (LLP) Listing

	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	59B348	1,531	17,469
Disk, 2 nd Stg.	3013712	56B965	1,531	22,469
Disk, 3 rd Stg.	3011713	A0002E09	1,531	23,469
Impeller	3013176	7D403	5,483	13,517
Disk, CT	3013411	9H144	7,787	8,213
PT Disk, 1 st Stg.	3022412	27B364	4,266	15,734

Key: TBA = To be assigned, N/A = Not Applicable

Accessories

	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003-01	119045	UNKNOWN
FUEL PUMP	025323-101-03	6101	UNKNOWN
FUEL CONTROL UNIT	3244834-3-2	41793	UNKNOWN
START FUEL CONTROL	3019109	11632	1,492.6
OIL/FUEL HEATER	10552E	797	1,492.6
COMP. BLEED VALVE	3100829-03	A4462	UNKNOWN

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.