



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	13,396.2	TSO:	0.0	W/O#:	10490
PCE:	PC0464	CSN:	26,254	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	35B394	15,030	3,970
Disk, 2 nd Stg.	3013712	11A091	10,761	13,239
Disk, 3 rd Stg.	3011713	11A988	10,761	14,239
Impeller	3027798	EAAA000C206	9,038	9,962
Disk, CT	3013411	18B402	10,158	5,842
PT Disk, 1 st Stg.	3026812	A001E8F4	9,560	10,440

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002	1812047	0.0
FUEL PUMP	702801-5	001385	0.0
FUEL CONTROL UNIT	3244897-4	C65621	0.0
FLOW DIVIDER	25536-4	21234	0.0
OIL/FUEL HEATER	10552E	4253	0.0
COMP. BLEED VALVE	540-1407-4	2282	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.