



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-28	TSN:	GG: 29,478.3 PS: 26,494.4	TSO:	GG: 3,303.5 PS: 3,303.5	W/O#:	11059
PCE:	GG: 50047 PS: 50047	CSN:	GG: 31,572 PS: 28,669	CSO:	GG: 3,858 PS: 3,858	TSHS:	1,800

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	34B657	12,651	6,349
Disk, 2 nd Stg.	3013712	A1102	17,925	6,075
Disk, 3 rd Stg.	3011713	A001PY0K	18,208	6,792
Impeller	3013176	EAAB000C103	17,368	1,632
Disk, CT	3013411	8X130	13,174	2,826
PT Disk, 1 st Stg.	3022412	A3754	18,821	1,179

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1284812	3,303.5
FUEL PUMP	025323-101-03	10165	3,303.5
FUEL CONTROL UNIT	2524440-7-6	A-74994	3,303.5
START FLOW CONTROL	3019109/25234-5	9959538014	3,313.5
OIL/FUEL HEATER	10552E	WA14100	3,313.5
COMP. BLEED VALVE	3100829-03	6C927	3,303.5

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

FINAL