



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

**ATS Form# 1024**

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-27I-28</b>	TSN:	GG: 15,002.8 PS: 27,124.2	TSO:	GG: 0.0 PS: 0.0	W/O#:	<b>10607</b>
PCE:	GG: 50272 PS: 52520-100	CSN:	GG: 20,301 PS: 55,218	CSO:	GG: 0.0 PS: 0.0	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	A0340	17,201	2,069
Disk, 2 <sup>nd</sup> Stg.	3013712	4312	21,330	2,670
Disk, 3 <sup>rd</sup> Stg.	3011713	A00050WE	23,076	1,924
Impeller	3013176	A1941	16,839	2,161
Disk, CT	3013411	88A536	15,234	766
PT Disk, 1 <sup>st</sup> Stg.	3022412	A2935	16,839	3,161

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002 AE	2244559	0.0
FUEL PUMP	025323-101-03	9825	0.0
FUEL CONTROL UNIT	3244786-6-5	B32174	0.0
START FLOW CONTROL	3019109	15254	0.0
OIL/FUEL HEATER	10552E	301	0.0
COMP. BLEED VALVE	3100829-03	A6196	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.