



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-65B	TSN:	GG: 27,455.9 PS: 26,340.8	TSO:	GG: 0.0 PS: 0.0	W/O#:	TBA
PCE:	GG: 32199 PS: 32296-100	CSN:	GG: N/A PS: N/A	CSO:	GG: 0.0 PS: 0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Disk, 1 st Stg.	3033601	TXA1C6423	4,644	19,356
Disk, 2 nd Stg.	3033512	22B266	12,078	11,922
Disk, 3 rd Stg.	3033513	33B102	12,078	11,922
Disk, 4 th Stg.	3033514	32B713	12,078	11,922
Spacer, 4 th Stg.	3114590-01	21B066	12,078	11,922
Impeller	3036897	4E185	17,060	6,940
Disk, CT	3040311	15B916	12,247	2,753
PT Disk, 1 st Stg.	3029312	52B358	11,794	18,206
PT Disk, 2 nd Stg.	3029313	93A813	13,715	16,285

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-310	2242048	0.0
FUEL PUMP	3033808	0580	0.0
FUEL CONTROL UNIT	8061-328	11451987	0.0
FLOW DIV/DUMP VALVE	25536-4	9959513555	0.0
OIL/FUEL HEATER	NOT VISIBLE	NOT VISIBLE	0.0
COMP. BLEED VALVE	3039031	7P164	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.