



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	GG: 20,795.9 PS: 25,789	TSO:	GG: 0.0 PS: 0.0	W/O#:	TBD
PCE:	GG: 56873 PS: 56465-100	CSN:	GG: 30,262 PS: 32,614	CSO:	GG: 0.0 PS: 0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	67A688	12,669	6,331
Disk, 2 nd Stg.	3013712	A001RDD8	13,123	10,877
Disk, 3 rd Stg.	3011713	11A146	18,994	6,006
Impeller	3013176	5A921	10,505	8,495
Disk, CT	3013411	8W863	12,761	3,239
PT Disk, 1 st Stg.	3026812	A002DY6N	10,695	9,305

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	2128619	0.0
FUEL PUMP	025323-101-03	15005	0.0
FUEL CONTROL UNIT	3244834-6-5-3-2	A25726	0.0
START FUEL CONTROL	3019109	14112	0.0
OIL/FUEL HEATER	10552E	WA17279	0.0
COMP. BLEED VALVE	3100829-03	H4266	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.