



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	5,230.7	TSO:	1,232.1	W/O#:	10921
PCE:	PH0179	S/F SN:	Starts: 5,399 Flights: 12,076	S/F SO:	Starts: 2,919 Flights: 4,022	TSHS:	1,203.9

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	9L004	2,896	16,104
Disk, 2 nd Stg.	3013712	9L384	8,957	15,043
Disk, 3 rd Stg.	3011713	9955	7,610	17,390
Impeller	3013176	A6649	4,631	14,369
Disk, CT	3013411	4HC05	10,616	5,384
PT Disk, 1 st Stg.	3026812	A00135L8	6,066	17,934

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1440198	0.0
FUEL PUMP	025323-101-03	2367	1,232.1
FUEL CONTROL UNIT	3244777-4-3-2	A48241	1,112.9
START FLOW CONTROL	25234-3	14232	1,232.1
OIL/FUEL HEATER	10552E	WA29048	1,232.1
COMP. BLEED VALVE	3100829-03	2C225	1,232.1

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

FINAL