



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	4,637.8	TSO:	0.0	W/O#:	11283
PCE:	PH1161	CSN:	Starts: 2,390 Flights: 7,668	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA02F295	1,482	17,518
Disk, 2 nd Stg.	3013712	A003YFH2	4,583	19,417
Disk, 3 rd Stg.	3011713	A003Y5BY	3,893	21,107
Impeller	3013176	CRAZAEXE117	2,665	16,335
Disk, CT	3013411	CRAZAEVB522	5,106	10,894
PT Disk, 1 st Stg.	3026812	YUAB001H020	2,918	21,082

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	20634423	0.0
OVERSPEED GOVERNOR	210507	14695889	0.0
FUEL PUMP	3034794	004730	0.0
FUEL CONTROL UNIT	4138008-3	F76571	0.0
FLOW DIVIDER/DUMP VALVE	25536-4	L1353	0.0
OIL/FUEL HEATER	10552E	WA54701	0.0
IGNITOR BOX	3035889	NNA16430251	0.0
COMP. BLEED VALVE	3105436-01	AHX1504693	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.