



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27	TSN:	11,597.7	TSO:	0.0	W/O#:	TBA
PCE:	42737	CSN:	8,766	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	66A121	8,766	10,234
Disk, 2 nd Stg.	3013712	69A978	8,766	15,234
Disk, 3 rd Stg.	3011713	68A443	8,766	16,234
Impeller	3013176	6E066	8,766	10,234
Disk, CT	3013411	65A038	8,766	7,234
PT Disk, 1 st Stg.	3022412	64A268	8,766	11,234

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	1704733	0.0
FUEL PUMP	386101-5	0114	0.0
FUEL CONTROL UNIT	3244786-6-2	A7538	0.0
START FLOW CONTROL	25234-5	14791	0.0
OIL/FUEL HEATER	10552E	WA2844	0.0
COMP. BLEED VALVE	3100829-03	17A556	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.