



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	12,075.4	TSO:	0.0	W/O#:	TBA
PCE:	PC2050	CSN:	15,893	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	73B364	7,356	11,644
Disk, 2 nd Stg.	3013712	A0019614	7,356	16,644
Disk, 3 rd Stg.	3011713	A0019CMO	7,356	17,644
Impeller	3027798	58B524	10,126	8,874
Disk, CT	3013411	A0019F15	7,356	8,644
PT Disk, 1 st Stg.	3026812	A0019H3C	7,356	12,644

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	11407543	0.0
FUEL PUMP	702801-5	003375	0.0
FUEL CONTROL UNIT	3244897-4	C655	0.0
FLOW DIVIDER	25536-4	9959559351	0.0
OIL/FUEL HEATER	10552E	WA45270	0.0
COMP. BLEED VALVE	540-1407-4	4878	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.