



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|---------|------|---------|------|-----|-------|-------|
| PT6A: | -27/-28 | TSN: | 7,788.8 | TSO: | 0.0 | W/O#: | 11374 |
| PCE: | 52318 | CSN: | 7,767 | CSO: | 0 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|---|---------|----------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 9E202 | 7,767 | 11,233 |
| Disk, 2 nd Stg. | 3013712 | 1E456 | 7,767 | 16,233 |
| Disk, 3 rd Stg. | 3011713 | 4H526 | 7,767 | 17,233 |
| Impeller | 3013176 | 8A882 | 7,767 | 11,233 |
| Disk, CT | 3013411 | 3K884 | 8,916 | 7,084 |
| PT Disk, 1 st Stg. | 3026812 | A0019L97 | 7,914 | 12,086 |
| Key: TBA = To be assigned, N/A = Not Applicable | | | | |

| Accessories | | | |
|---|---------------|--------|-----|
| | P/N | S/N | TSO |
| FUEL PUMP | 025323-101-03 | 8712 | 0.0 |
| FUEL CONTROL UNIT | 2524440-5 | A66170 | 0.0 |
| START FLOW CONTROL | 25234-2 | 11936 | 0.0 |
| OIL/FUEL HEATER | 10552E | 171 | 0.0 |
| COMP. BLEED VALVE | 3100829-03 | 17A544 | 0.0 |
| Key: TBA = To be assigned, N/A = Not Applicable | | | |

Comments: All engines ship FOB ATS dock