



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	13,455.8	TSO:	0.0	W/O#:	8357
PCE:	57425	CSN:	Starts: N/A Flights: N/A	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1X194	3,983	15,017
Disk, 2 nd Stg.	3013712	11A090	7,969	16,031
Disk, 3 rd Stg.	3011713	11A225	7,083	17,917
Impeller	3013176	8F183	6,100	12,900
Disk, CT	3013411	TBD	TBD	8,000
PT Disk, 1 st Stg.	3026812	30A994	9,885	14,115

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1586380	0.0
FUEL PUMP	025323-101-03	14253	0.0
FUEL CONTROL UNIT	2524440-8-6	A59271	0.0
START FLOW CONTROL	25234-3	14486	0.0
OIL/FUEL HEATER	10552E	WA14236	0.0
COMP. BLEED VALVE	3105436-01	28A489	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.