



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	12,765.8	TSO:	0.0	W/O#:	10939
PCE:	PC0499	CSN:	13,825	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	35B390	13,825	5,175
Disk, 2 nd Stg.	3013712	37B320	13,825	10,175
Disk, 3 rd Stg.	3011713	37B571	13,825	11,175
Impeller	3027798	7F883	13,825	5,175
Disk, CT	3013411	39B667	13,825	2,175
PT Disk, 1 st Stg.	3026812	39B556	13,825	6,175

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	1567708	0.0
FUEL PUMP	025323-150	954	0.0
FUEL CONTROL UNIT	32448974	B10793	0.0
FLOW DIVIDER	25536-4	9972	0.0
OIL/FUEL HEATER	10552E	WA8585	0.0
COMP. BLEED VALVE	540-1407-4	5459	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.