



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	GG: 25,756.2 PS: 25,797.4	TSO:	GG: 9,398.8 PS: 9,394.4	W/O#:	TBA
PCE:	GG: 56864 PS: 56871-100	CSN:	GG: 43,108 PS: 43,224	CSO:	GG: 16,060 PS: 16,060	TSHS:	UNKNOWN

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	6069	14,533	4,467
Disk, 2 nd Stg.	3013712	82A864	19,119	4,881
Disk, 3 rd Stg.	3011713	A001TKED	7,967	17,033
Impeller	3013176	6A309	14,729	4,271
Disk, CT	3013411	NOT INCLUDED	NOT INCLUDED	NOT INCLUDED
PT Disk, 1 st Stg.	3022412	9P215	14,200	5,800
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-003	TBD	TBD
FUEL PUMP	025323-101-03	TBD	TBD
FUEL CONTROL UNIT	3244834-1	TBD	TBD
START FLOW CONTROL	3019109	TBD	TBD
OIL/FUEL HEATER	10552E	TBD	TBD
COMP. BLEED VALVE	3100829-03	TBD	TBD
Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.			

Comments: All engines ship FOB ATS dock.